

State or Territory	Web Address	3t & Under (forks attached)	Over 3t (forks attached)	Attachments WP Basket less than 11m	Attachments WP Basket 11m or over	Jib or Hook maximum capacity 3t & under	Jib or Hook maximum capacity over 3t	Slewing TH Any Capacity
ACT	www.legislation.act.gov.au	DOC	CN	DOC	WP	DOC	CN#	C2/C6/C1/C0
NSW	www.workcover.nsw.gov.au	DOC	DOC	DOC	WP	DOC	CN#	C2/C6/C1/C0
NT	www.worksafe.nt.gov.au	DOC	DOC	DOC	WP	DOC	CN#	C2/C6/C1/C0
QLD	www.deir.qld.gov.au	DOC	DOC	DOC	WP	DOC	CN#	Note 1
SA	www.safework.sa.gov.au	DOC	DOC	DOC	WP	DOC	CN#	C2/C6/C1/C0
TAS	www.wst.tas.gov.au	DOC	DOC	DOC	WP	DOC	CN#	Note 1
VIC	www.worksafe.vic.gov.au	DOC	CN	DOC	WP	DOC	CN#	Note 1
WA	www.worksafe.wa.gov.au	DOC	DOC	DOC	WP	DOC	CN#	Note 1
	Type of Load Management Systems Required	LSL/LSI	LSL/LSI	Note 2	Note 2	LSL/LSI and MCL or RCL/RCI Note 3	RCL/RCI Note 3	RCL/RCI

Note 1: Although not stated as such a C2 / C6 / C1 / C0 would be the requirement as CN is non-slewing. Check with State Regulator

Note 2: Platform attachment recognition required on TH and Slewing TH's fitted with work platforms. WP Baskets must not be mounted to fork tynes

Note 3: Jib or hook maximum capacity is determined by the combination of the TH and the attachment and rated as such on the related load chart. All attachment combinations must be approved for use on the TH and the appropriate load charts provided

Legend: TH = Telescopic Handler

DOC = Duty of Care Training: eg EWPA Gold Card

CN = Licence: Non-slewing Crane over 3t

C2/C6/C1/C0 = Licence: Cranes, Slewing

WP = Licence: Elevating Work Platform Boom 11m & over

LF = Licence: Forklift

RCL/RCI = Rated Capacity Limiter/Indicator

LSL/LSI = Longitudinal Stability Limiter/Indicator

MCL = Maximum Capacity Limiter

CN is the minimum required licence. Note that C2/C6/C1/C0 are also acceptable.

CONTACT: TSHA Inc:

Webpage: www.tsha.com.au

Email: info@tsha.com.au

Phone: 02 9998 2222

Disclaimer: Check with your State Regulator. This document is a guide only and is subject to change.